



# METROPOLITAN WASHINGTON AIRPORTS AUTHORITY

## RFP No. 1-18-C046 Concourse C/D Skylights, Roof Top Units, and Boilers Replacement at Dulles Airport

April 30, 2018

### Questions and Answers

**Notice:** Questions may have been edited for clarity and relevance.

- 1. Question:** Is a separate full-time QC Manager required, or can the Project Manager or Superintendent fill this role?

**Answer:** The Superintendent can fill the role of QC Manager while the Project Manager cannot fill the role of QC Manager.
- 2. Question:** This proposal requires Past Performance Questionnaires. Several of our relevant projects are proprietary and our clients will not fill out PPQs, however they are open to receiving phone calls for references. Can you amend the PPQ requirement to allow us to submit Reference information?

**Answer:** Past Performance Questionnaires are required as noted in the RFP.
- 3. Question:** Can you please provide the size of the circular skylights?

**Answer:** There are approximately 37 skylights of various dimensions. Those firms short listed will be provided a site visit at which time the actual skylight dimensions can be obtained for purposes of submitting pricing.
- 4. Question:** This proposal requires new Past Performance Questionnaires for each submitted project. Our clients that have already submitted one (or several) PPQs do not like to be continually asked for new PPQs. Can we submit a prior PPQ for our relevant experience as long as it doesn't reference prior solicitations

**Answer:** Past Performance Questionnaires are required as noted in the RFP.